

# **INSTRUCTIONS**

# **175-06**

## **LINING REPLACEMENT**

### **CAUTION!**

**WEAR ADEQUATE EYE PROTECTION, GLOVES AND CLOTHING,  
BRAKE FLUID MAY CAUSE EYE IRRITATION. IN CASE OF EYE  
CONTACT, FLUSH WITH WATER FOR 20 MINUTES AND GET  
IMMEDIATE MEDICAL ATTENTION.**

Remove screws that fasten two halves of caliper together. Take care to avoid losing O-rings. (O-rings must be re-installed in re-assembly).

Remove old linings from pistons. Press pistons back into caliper housing halves until they contact the back of the boxes. Scrape all adhesive from piston faces. Apply new adhesive. Install new linings. Firmly seat new linings against pistons. Re-assemble calipers with original O-rings in proper positions between halves. Install assembly screws and torque to 18 - 20 ft. lb. Bleed the hydraulic system thoroughly to remove all air.

**AIRHEART® BRAKE CO.**  
HAMEL, MN 55340, USA